



Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

810608

MN #42

MNS-000-001-040

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name International Business Machines Corp

Street 3605 Hwy 52 North

City Rochester

State MN

Zip Code 55901

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site

~~Same as above~~ INTERNATIONAL BUSINESS MACHINES CORP.

Street

EPA ID No: MND006161756 ^{OK} 3605 Hwy 52 North

City

ROCHESTER

County

Olmsted

State

MN

Zip Code

55901

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form

Name (Last, First and Title) Zitnay, Louis Environmental Engineer

Phone

(507) 286-0456

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year)

1958

To (Year)

1958

EPA Region 5 Records Ctr.



387827

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

- 1. ☐ Organics
- 2. ☐ Inorganics
- 3. ☐ Solvents
- 4. ☐ Pesticides
- 5. ☐ Heavy metals
- 6. ☐ Acids
- 7. ☐ Bases
- 8. ☐ PCBs
- 9. ☐ Mixed Municipal Waste
- 10. ☐ Unknown
- 11. ☐ Other (Specify)

Source of Waste:

Place an X in the appropriate boxes.

- 1. ☐ Mining
- 2. ☐ Construction
- 3. ☐ Textiles
- 4. ☐ Fertilizer
- 5. ☐ Paper/Printing
- 6. ☐ Leather Tanning
- 7. ☐ Iron/Steel Foundry
- 8. ☐ Chemical, General
- 9. ☐ Plating/Polishing
- 10. ☐ Military/Ammunition
- 11. ☐ Electrical Conductors
- 12. ☐ Transformers
- 13. ☐ Utility Companies
- 14. ☐ Sanitary/Refuse
- 15. ☐ Photofinish
- 16. ☐ Lab/Hospital
- 17. ☐ Unknown
- 18. ☐ Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

F006 *		
See note below	**	

* Wastewater Treatment Sludges from Electroplating Operations

** See Permit Application Part A for information on current treatment and storage operations at this site. Only information not included in the Part A Application has been noted on this form.

Notification of Hazardous Waste Site

Side Two

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☐ Landfill
4. ☐ Tanks
5. ☒ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet

gallons Estimate 2500 **B****Total Facility Area**square feet 25,000 **S**

acres

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☐ None

(Not suspected)

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

SEE ATTACHED SKETCH

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

For 3-4 months in 1958, before the industrial waste treatment plant was completed, treated plating rinse waters were discharged to the impoundment.

The treated rinses had undergone chrome reduction, cyanide oxidation and lime neutralization before being pumped to the impoundment.

The impoundment was never used again and several years later it was filled in with earth.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required

Name John P Harmon, Manager Dept 713

Street Same as A

City

State

Zip Code

Signature

John Harmon

Date


6/8/81

☐ Owner, Present☐ Owner, Past☐ Transporter☒ Operator, Present☐ Operator, Past☐ Other

44

NOTIFICATION OF HAZARDOUS WASTE SITE

H - Sketch of Site Location



SKETCH

JUN 10 1981

IBM Rochester
3605 Hwy 52 N
Rochester, MN 55901

EPA ID No:
MND 006161756

IBM

Hwy. 52 & Northwest 37 Street
Rochester, MN 55901

Dept 713

US EPA Region 5
Sites Notification
Chicago, IL 60604

